

**West Bengal State Electricity Distribution Company Limited**  
**(A Government of West Bengal Enterprise)**  
**(IT & Communication Cell)**

Vidyut Bhavan, 3<sup>rd</sup> Floor, C&D Block, Bidhan Nagar, Block-DJ, Sec-II, Kolkata-700091  
Phone No.033-2358-9665, FAX No.033-2337-2427, 033-2358-9244  
Website: [www.wbsedcl.in](http://www.wbsedcl.in), e-mail: [itcell@wbsedcl.in](mailto:itcell@wbsedcl.in)  
CIN: U40109WB2007SGC113473

Memo no.: WBSEDCL/IT&C/33.10(i)/ 3501

Date: 26.02.2021

**NOTICE**

**Sub : - Clarification of pre-bid queries and Modification in BOQ**

**Ref : Tender Notice No: WBSEDCL/IT&C/33.10(i)/3429 Dated: 09.02.2021.**

Following queries have been received from M/s Vertiv regarding subjected tender. No queries have been received from any other vendors.

1) The clarification of the tender committee regarding the queries has been mentioned below.

Sl.	Ref. Clause / Point	Query from Vendor (VERTIV)	Reply from Customer (WBSEDCL)
1	SW.12.7.8, Anx-V, Sl.No. 39 to 42	All UPS battery of 160 KVA & 10KVA UPS will be replace from customer in extra PO basis as when required. Please confirm.	Batteries (Battery Bank) of 200/160 KVA UPS are not in the scope of this tender. However Batteries (Battery Bank) of 10KVA UPS are under the scope of this AMC and defective materials needs to be replaced by bidder if required without any extra cost to WBSEDCL.
2	Anx-V, Sl.No. 1 & 2	All 625 KVA DG set battery 2nos each DG set are in unhealthy condition and lower rating battery installed. And those DG set might be break down at any time. So, it has to be replace from customer end before starting of the contract. Please confirm.	The mentioned batteries are in working condition and under warranty. However Batteries are under the scope of this AMC and defective materials needs to be replaced by bidder if required without any extra cost to WBSEDCL.
3	Anx-V, Sl.No. 3 & 4	Currently Woodward controller of DG sync panel in not working, So, it has to replace by customer end before starting of the contract or Rectification of same to be mentioned as additional tender line item for replacement/up gradation. Please confirm.	Currently Woodward controller of DG sync panel is in working condition and running properly. However Woodward controllers are under the scope of this AMC and defective materials needs to be replaced by bidder if required without any extra cost to WBSEDCL.
4	Anx-V, Sl.No. 43 & 44	Some of PAC unit compressor, Condenser & Air Filter condition are in very bad condition due improper maintenance. So, it has to be replace from customer end before starting of	PACs are running 24*7*365 mode. All PACs are working properly and scheduled preventive maintenance are done.

		the contract or Rectification of same to be mentioned as additional tender line item for replacement/up gradation. Please confirm.	However PACs are under the scope of this AMC and defective materials needs to be replaced by bidder if required without any extra cost to WBSEDCL.
5	Anx-V, Sl.No. 47 - 50	Installed BMS & integration software are outdated as on today. So, urgently it need to upgrade otherwise, it not possible to give support upto 3yrs. So, it has to be replace from customer end before starting of the contract Or Rectification of same to be mentioned as additional tender line item for replacement/up gradation. Please confirm.	Though the BMS software are old, but these are in working condition and running absolutely fine. BMS systems are under the scope and if required, defective materials needs to be upgraded/Rectified without any extra cost to WBSEDCL.
6	Anx-V, Sl.No. 53 - 54	Installed Fire Alarm & Suppression system are out dated. So, urgently it need to upgrade otherwise, it not possible to give support upto 3yrs. So, it has to be replace from customer end before starting of the contract Or Rectification of same to be mentioned as additional tender line item for replacement/up gradation. Please confirm.	Though the Fire Alarm & Suppression system are old, but these are in working condition and running absolutely fine. The systems are under the scope and if required, defective materials needs to be upgraded/ Rectified without any extra cost to WBSEDCL.
7	Anx-V, Sl.No. 57, 58, 65 & 66	Installed VESDA & PA system are not working. So, it has to handover to vendor in working condition before starting of the contract Or Rectification of same to be mentioned as additional tender line item for replacement/up gradation. Please confirm.	Currently VESDA & PA system is in working condition and running properly.  The systems are under the scope and if required, defective materials needs to be upgraded/Replaced/ Rectified without any extra cost to WBSEDCL.
8	Anx-V, Sl.No. 59 & 60	Installed Access Control System are partially working. Now the biometric are in break down condition. So, it has to handover to vendor in working condition before starting of the contract Or Rectification of same to be mentioned as additional tender line	The system is fully functional and will be handed over to the successful bidder in working condition at the beginning of the contract.  The systems are under the scope and if required, defective materials

		item for replacement/up gradation. Please confirm.	needs to be upgraded/replaced/ Rectified without any extra cost to WBSEDCL.
9	Anx-V, Sl.No. 63 & 64	In both site, the analog CCTV system installed. But if in future any camera issue arise then the entire system has to be upgrade. So, we suggest to upgrade the CCTV DVR to CCTV NVR system along with IP based camera from your end Or Up gradation of same to be mentioned as additional tender line item for replacement/up gradation. Please confirm	In DC and DRC analog CCTV systems are installed. The system is in working condition and running absolutely fine. The systems are under the scope of this AMC and needs to be replaced/ rectified/Upgraded time to time by the successful bidder if required without any extra cost to WBSEDCL
10	Anx-II, Sl.No. 6 (Mandatory Condition)	We are agree to repair / replace the defective equipments / materials under this NieT with equipments / materials of equivalent or higher specification of same or equivalent make. And the same must be compatible with WBSEDCL's existing system without any trouble. Please confirm the changes in condition.	Vendor should agree to repair / replace the defective equipments / materials under this NieT with equipments / materials of Equivalent or higher specification of same make. The replaced equipment / material should run in WBSEDCL's existing running system without any trouble.
11	Anx-II, Sl.No. 5 (Mandatory Condition)	Here, the back end agreement with major OEM i.e. Jackson which mean to say the DG OEM i.e. Cummins. Is it correct? Please confirm.	back end agreement with Jackson/Cummins

**Entire system will be handed over to successful bidder in fully working condition.**

- 2) The BOQ has been modified and uploaded considering line item no 68 and 69, Manpower cost for DC and DRC.

**All the other terms and conditions of the tender will remain same.**



**P. Bhattacharjee**  
Chief Engineer, IT&C Cell  
WBSEDCL